



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

EOP-3

Lab# 2561

Customer

Facility Name: Waterdam
Address: 524 Waterdam Rd.
Cannonsburg, PA 15317

Sample Collection

Date: 5/18/26
Time: 1:03 PM
Method: Grab

Sample Final Analysis

Date: 5/20/26
Time: 11:30 AM
Analyst: AS

Matrix: Recreational Water
Source Type: Pool

Laboratory Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	5/19/26 11:00 AM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/19/26 11:00 AM	SL	SM 9222B
Standard plate count:	0/ml	200/ml	5/18/26 5:50 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.3 SU	7.2 - 7.8 SU	5/18/26 1:03 PM	SL	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	5/18/26 1:03 PM	SL	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/18/26 1:03 PM	SL	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor