



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

N-15

Lab# 2634

Customer

Facility Name: Village Cranberry Woods Apt.

Address: 5001 Pendleton Way
Cranberry, PA 16066

Matrix: Recreational Water

Source Type: Pool

Sample Collection

Date: 6/2/26

Time: 12:40 PM

Method: Grab

Sample Final Analysis

Date: 6/4/26

Time: 11:30 AM

Analyst: AS

Accredited Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	6/3/26 11:00 AM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	6/3/26 11:00 AM	SL	SM 9222B
Standard plate count:	0/ml	200/ml	6/2/26 6:30 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	6/2/26 12:40 PM	EG	DPD
Chlorine:	2.0 mg/l	1.0 - 5.0 mg/l	6/2/26 12:40 PM	EG	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/2/26 12:40 PM	EG	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)