



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

Service

Lab# 311

Customer

Facility Name: UPMC Lemieux Sports Complex

Address: 8000 Cranberry Springs Drive
Cranberry Township, PA 16066

Matrix: Recreational Water

Source Type: Spa

Sample Collection

Date: 6/23/26

Time: 10:30 AM

Method: Grab

Sample Final Analysis

Date: 6/25/26

Time: 11:00 AM

Analyst: AS

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	6/24/26	10:30 AM	MD	SM 9222G

Total coliforms:	0/100mls	2/100mls	6/24/26	10:30 AM	MD	SM 9222B
------------------	----------	----------	---------	----------	----	----------

Standard plate count:	50/ml	200/ml	6/23/26	5:30 PM	SL	SM 9215B
-----------------------	-------	--------	---------	---------	----	----------

Additional Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Fecal Streptococcus	0/100mls	2/100mls	6/24/26	2:25 PM	AH	SM 9230C

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.3 SU	7.2 - 7.8 SU	6/23/26	10:30 AM	JL	DPD
Chlorine:	4.2 mg/l	1.0 - 5.0 mg/l	6/23/26	10:30 AM	JL	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/23/26	10:30 AM	JL	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)