



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2051

Customer

American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: Bower Hill at Mt. Lebanon

Date: 6/22/26

Address: 1150 Bower Hill Road
Pittsburgh, PA 15243

Time: 12:50 PM

Method: Grab

Sample Final Analysis

Matrix: Recreational Water

Date: 6/24/26

Time: 12:00 PM

Source Type: Pool

Analyst: AS

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	6/23/26	11:30 AM	MD	SM 9222G
Total coliforms:	0/100mls	2/100mls	6/23/26	11:30 AM	MD	SM 9222B
Standard plate count:	570/ml	200/ml	6/22/26	5:00 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	6/22/26	12:50 PM	JB	DPD
Chlorine:	6.0 mg/l	1.0 - 5.0 mg/l	6/22/26	12:50 PM	JB	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/22/26	12:50 PM	JB	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)