



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

S-12

Lab# 016

Customer

Facility Name: *Baldwin H.S.*
Address: *4653 Clairton Boulevard*
Pittsburgh, PA 15236

Matrix: *Recreational Water*
Source Type: *Deep End*

Sample Collection

Date: *5/13/26*
Time: *10:37 AM*
Method: *Grab*

Sample Final Analysis

Date: *5/15/26*
Time: *4:00 PM*
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	5/13/26 3:36 PM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/13/26 3:36 PM	SL	SM 9222B
Standard plate count:	50/ml	200/ml	5/13/26 3:32 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	5/13/26 10:37 AM	SL	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	5/13/26 10:37 AM	SL	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/13/26 10:37 AM	SL	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)