



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

N-13

Lab# 088

Customer

Facility Name: *Divine Providence*
Address: *9000 Babcock Blvd.*
Allison Park, PA 15101

Sample Collection

Date: *5/19/26*
Time: *2:02 PM*
Method: *Grab*

Sample Final Analysis

Date: *5/22/26*
Time: *11:30 AM*
Analyst: *AS*

Matrix: *Recreational Water*

Source Type: *Pool*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	5/20/26 11:00 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/20/26 11:00 AM	AH	SM 9222B
Standard plate count:	0/ml	200/ml	5/19/26 5:40 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.8 SU	7.2 - 7.8 SU	5/19/26 2:02 PM	AMH	DPD
Chlorine:	5.0 mg/l	1.0 - 5.0 mg/l	5/19/26 2:02 PM	AMH	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/19/26 2:02 PM	AMH	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor