



**Dream Pools and Spas**  
**1105 Washington Blvd**  
**Pittsburgh, Pennsylvania 15206**  
**(412) 661- 7665**  
**Laboratory Analysis Report**

Lab ID No. 02-04041

**N-17**

**Lab# 390**

**Customer**

**Facility Name:** *Fairfield Inn & Suites*  
**Address:** *1000 University Parkway*  
*Slippery Rock, PA 16057*

**Matrix:** *Recreational Water*

**Source Type:** *Spa*

**Sample Collection**

**Date:** *6/23/26*  
**Time:** *10:53 AM*  
**Method:** *Grab*

**Sample Final Analysis**

**Date:** *6/26/26*  
**Time:** *12:00 PM*  
**Analyst:** *AS*

| Accredited Analysis | Results | Reporting limit | Incubation Date/Time | Analyst | Method |
|---------------------|---------|-----------------|----------------------|---------|--------|
|---------------------|---------|-----------------|----------------------|---------|--------|

|                       |          |          |                  |    |          |
|-----------------------|----------|----------|------------------|----|----------|
| Escherichia Coli:     | Absent   | Absent   | 6/24/26 11:30 AM | MD | SM 9222G |
| Total coliforms:      | 0/100mls | 2/100mls | 6/24/26 11:30 AM | MD | SM 9222B |
| Standard plate count: | 0/ml     | 200/ml   | 6/23/26 6:20 PM  | SL | SM 9215B |

| Additional Analysis | Results | Reporting limit | Incubation Date/Time | Analyst | Method |
|---------------------|---------|-----------------|----------------------|---------|--------|
|---------------------|---------|-----------------|----------------------|---------|--------|

|                     |          |          |                 |    |          |
|---------------------|----------|----------|-----------------|----|----------|
| Fecal Streptococcus | 0/100mls | 2/100mls | 6/24/26 2:25 PM | AH | SM 9230C |
|---------------------|----------|----------|-----------------|----|----------|

| Field Analysis | Results | Reporting limit | Date/Time | Analyst | Method |
|----------------|---------|-----------------|-----------|---------|--------|
|----------------|---------|-----------------|-----------|---------|--------|

|            |          |                |                  |    |        |
|------------|----------|----------------|------------------|----|--------|
| pH:        | 7.4 SU   | 7.2 - 7.8 SU   | 6/23/26 10:53 AM | MM | DPD    |
| Chlorine:  | 2.5 mg/l | 1.0 - 5.0 mg/l | 6/23/26 10:53 AM | MM | DPD    |
| Turbidity: | 1 NTU    | 1 - 2 NTU      | 6/23/26 10:53 AM | MM | Visual |

**Sample comments**

*Andre Smith*

Andre Smith, Lead Supervisor

( When exceeding reporting limit pool or spa is unfit)