



**Dream Pools and Spas**  
**1105 Washington Blvd**  
**Pittsburgh, Pennsylvania 15206**  
**(412) 661- 7665**  
**Laboratory Analysis Report**

Lab ID No. 02-04041

**N-14**

**Lab# 2719**

**Customer**

**Facility Name:** Meeder Flats  
**Address:** 1000 Strand Road  
Cranberry, PA 16066

**Sample Collection**

**Date:** 6/17/26  
**Time:** 3:05 PM  
**Method:** Grab

**Sample Final Analysis**

**Date:** 6/20/26  
**Time:** 10:30 AM  
**Analyst:** AS

**Matrix:** Recreational Water

**Source Type:** Spa

| Accredited Analysis | Results | Reporting limit | Incubation Date/Time | Analyst | Method |
|---------------------|---------|-----------------|----------------------|---------|--------|
|---------------------|---------|-----------------|----------------------|---------|--------|

|                       |          |          |                  |    |          |
|-----------------------|----------|----------|------------------|----|----------|
| Escherichia Coli:     | Absent   | Absent   | 6/18/26 10:00 AM | SL | SM 9222G |
| Total coliforms:      | 0/100mls | 2/100mls | 6/18/26 10:00 AM | SL | SM 9222B |
| Standard plate count: | 70/ml    | 200/ml   | 6/17/26 4:45 PM  | SL | SM 9215B |

| Additional Analysis | Results | Reporting limit | Incubation Date/Time | Analyst | Method |
|---------------------|---------|-----------------|----------------------|---------|--------|
|---------------------|---------|-----------------|----------------------|---------|--------|

|                     |          |          |                  |    |          |
|---------------------|----------|----------|------------------|----|----------|
| Fecal Streptococcus | 0/100mls | 2/100mls | 6/18/26 10:00 AM | SL | SM 9230C |
|---------------------|----------|----------|------------------|----|----------|

| Field Analysis | Results | Reporting limit | Date/Time | Analyst | Method |
|----------------|---------|-----------------|-----------|---------|--------|
|----------------|---------|-----------------|-----------|---------|--------|

|            |          |                |                 |    |        |
|------------|----------|----------------|-----------------|----|--------|
| pH:        | 7.2 SU   | 7.2 - 7.8 SU   | 6/17/26 3:05 PM | EG | DPD    |
| Chlorine:  | 2.0 mg/l | 1.0 - 5.0 mg/l | 6/17/26 3:05 PM | EG | DPD    |
| Turbidity: | 1 NTU    | 1 - 2 NTU      | 6/17/26 3:05 PM | EG | Visual |

**Sample comments**

Andre Smith, Lead Supervisor

( When exceeding reporting limit pool or spa is unfit)