



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 2

Lab# 2226

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Glencannon* *Date:* *7/28/26*
Address: *207 Driftwood Road* *Time:* *12:40 PM*
Canonsburg, PA 15317 *Method:* *Grab*

Sample Final Analysis

Matrix: *Recreational Water* *Date:* *7/31/26*
Source Type: *Wading Pool* *Time:* *11:00 AM*
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	7/29/26	10:40 AM	MD	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/29/26	10:40 AM	MD	SM 9222B
Standard plate count:	0/ml	200/ml	7/28/26	6:00 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	7/28/26	12:40 PM	EB	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	7/28/26	12:40 PM	EB	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/28/26	12:40 PM	EB	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)