



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2082

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Carriage Park Apt.*
Address: *300 Chatham Park Dr.*
 Pittsburgh, PA 15220

Date: 6/29/26
Time: 10:28 AM
Method: *Grab*

Sample Final Analysis

Matrix: *Recreational Water*
Source Type: *Shallow End*

Date: 7/1/26
Time: 12:00 PM
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	6/30/26	11:30 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	6/30/26	11:30 AM	AH	SM 9222B
Standard plate count:	20/ml	200/ml	6/29/26	5:50 PM	SL	SM 9215B
Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	6/29/26	10:28 AM	SL	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	6/29/26	10:28 AM	SL	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/29/26	10:28 AM	SL	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)