



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2056

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Facility Name: *Brentwood Borough Pool*

Address: *Park Dr.*
Pittsburgh, PA 15227

Sample Collection

Date: 7/21/26
Time: 10:30 AM
Method: *Grab*

Matrix: *Recreational Water*

Sample Final Analysis

Date: 7/24/26
Time: 11:30 AM
Analyst: AS

Source Type: *Deep End*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	7/22/26	11:00 AM	AS	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/22/26	9:40 AM	AS	SM 9222B
Standard plate count:	0/ml	200/ml	7/21/26	6:30 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	7/21/26	10:30 AM	AHV	DPD
Chlorine:	10.0 mg/l	1.0 - 5.0 mg/l	7/21/26	10:30 AM	AHV	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/21/26	10:30 AM	AHV	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)