



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2059

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Bright Oaks*

Date: *7/21/26*

Address: *600 N. Branch Road*
Oakdale, PA 15071

Time: *8:05 AM*

Method: *Grab*

Sample Final Analysis

Matrix: *Recreational Water*

Date: *7/24/26*

Time: *10:00 AM*

Source Type: *Pool*

Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	7/22/26	9:40 AM	AS	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/22/26	9:40 AM	AS	SM 9222B
Standard plate count:	0/ml	200/ml	7/21/26	4:30 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	8.0 SU	7.2 - 7.8 SU	7/21/26	8:05 AM	AHM	DPD
Chlorine:	2.5 mg/l	1.0 - 5.0 mg/l	7/21/26	8:05 AM	AHM	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/21/26	8:05 AM	AHM	Visual

Sample comments

Andre Smith

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)