



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2423

Customer

American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: Apartment at North Park

Date: 7/8/26

Address: 9815 Presidential Dr.
Allison Park, PA 15101

Time: 10:21 AM

Method: Grab

Sample Final Analysis

Matrix: Recreational Water

Date: 7/10/26

Source Type: Pool

Time: 2:30 PM

Analyst: AS

Accredited Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	7/9/26 2:00 PM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/9/26 2:00 PM	SL	SM 9222B
Standard plate count:	5700/ml	200/ml	7/8/26 6:10 PM	SL	SM 9215B
Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	7/8/26 10:21 AM	MM	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	7/8/26 10:21 AM	MM	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/8/26 10:21 AM	MM	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor