Lab ID No. 02-04041

Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Service

Lab# 312

Customer

Facility Name:	*UPMC Lemieux Sports Complex*
Address:	*8000 Cranberry Springs Drive* *Cranberry Township, PA 16066*
Matrix:	*Recreational Water*
Source Type:	*Cold Plunge*

Sample Collection

Date:	*2/24/26*
Time:	11:15 AM
Method:	*Grab*

Sample Final Analysis

Date:	*2/26/26*
Time:	*10:30 AM*
Analyst:	*AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	2/25/26	10:00 AM	JC	SM 9222G
Total coliforms:	0/100mls	2/100mls	2/25/26	10:00 AM	JC	SM 9222B
Standard plate count:	20/ml	200/ml	2/24/26	5:00 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	2/24/26	11:15 AM	JR	DPD
Chlorine:	4.0 mg/l	1.0 - 5.0 mg/l	2/24/26	11:15 AM	JR	DPD
Turbidity:	1 NTU	1 - 2 NTU	2/24/26	11:15 AM	JR	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith

Andre Smith, Lead Supervisor