



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206 **Service**
(412) 661-7665
Laboratory Analysis Report **Lab# 312**

Lab ID No. 02-04041

Customer

Facility Name: *UPMC Lemieux Sports Complex*

Address: *8000 Cranberry Springs Drive*
 Cranberry Township, PA 16066

Matrix: *Recreational Water*

Source Type: *Cold Plunge*

Sample Collection

Date: *5/19/26*
Time: *12:11 PM*
Method: *Grab*

Sample Final Analysis

Date: *5/21/26*
Time: *11:30 AM*
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation	Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	5/20/26	11:00 AM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/20/26	11:00 AM	SL	SM 9222B
Standard plate count:	0/ml	200/ml	5/19/26	7:20 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	5/19/26	12:11 PM	RD DPD
Chlorine:	3.2 mg/l	1.0 - 5.0 mg/l	5/19/26	12:11 PM	RD DPD
Turbidity:	1 NTU	1 - 2 NTU	5/19/26	12:11 PM	RD Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor