



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

N-13

Lab# 2558

Customer

Facility Name: *Waldorf Tower*
Address: *103 McKnight Circle*
Pittsburgh, PA 15237

Sample Collection

Date: *5/27/26*
Time: *11:10 AM*
Method: *Grab*

Sample Final Analysis

Date: *5/29/26*
Time: *10:30 AM*
Analyst: *AS*

Matrix: *Recreational Water*
Source Type: *Pool*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	5/28/26	10:00 AM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/28/26	10:00 AM	SL	SM 9222B
Standard plate count:	150/ml	200/ml	5/27/26	5:53 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	8.0 SU	7.2 - 7.8 SU	5/27/26	11:10 AM	IS	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	5/27/26	11:10 AM	IS	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/27/26	11:10 AM	IS	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor