



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 4

Lab# 2639

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Facility Name: *Village of Easton*

Address: *6000 Beatty Dr.*
Irwin, PA 15642

Matrix: *Recreational Water*

Source Type: *Pool*

Sample Collection

Date: *6/10/26*

Time: *10:45 AM*

Method: *Grab*

Sample Final Analysis

Date: *6/12/26*

Time: *10:30 AM*

Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	6/11/26	10:10 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	6/11/26	10:10 AM	AH	SM 9222B
Standard plate count:	0/ml	200/ml	6/10/26	6:10 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	6/10/26	10:45 AM	LL	DPD
Chlorine:	7.5 mg/l	1.0 - 5.0 mg/l	6/10/26	10:45 AM	LL	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/10/26	10:45 AM	LL	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor