



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041
APM 2

Lab# 2113

Customer

American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Clinton Lake*

Date: *6/16/26*

Time: *1:53 PM*

Address: *124 Clinton Dr.*
Clinton, PA 15026

Method: *Grab*

Sample Final Analysis

Matrix: *Recreational Water*

Date: *6/18/26*

Time: *11:30 AM*

Source Type: *Pool*

Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	6/17/26	11:00 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	6/17/26	11:00 AM	AH	SM 9222B
Standard plate count:	0/ml	200/ml	6/16/26	4:30 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	6/16/26	1:53 PM	AH	DPD
Chlorine:	2.0 mg/l	1.0 - 5.0 mg/l	6/16/26	1:53 PM	AH	DPD
Turbidity:	1 NTU	1 - 2 NTU	6/16/26	1:53 PM	AH	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor