



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2102

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Cherry Hill* **Date:** *7/29/26*
Address: *2100 Cherry Hill Dr.* **Time:** *9:45 AM*
Nevillewood, PA 15142 **Method:** *Grab*

Sample Final Analysis

Matrix: *Recreational Water* **Date:** *8/1/26*
Source Type: *Pool* **Time:** *10:00 AM*
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	7/30/26	9:30 AM	MD	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/30/26	9:30 AM	MD	SM 9222B
Standard plate count:	0/ml	200/ml	7/29/26	5:45 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	7/29/26	9:45 AM	JB	DPD
Chlorine:	7.5 mg/l	1.0 - 5.0 mg/l	7/29/26	9:45 AM	JB	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/29/26	9:45 AM	JB	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)