



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 3

Lab# 2275

Customer

*American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237*

Facility Name: Hunt Club At Grandview

*Address: 312 Saddlebrook Rd.
West Deer, PA 15044*

Matrix: Recreational Water

Source Type: Pool

Sample Collection

*Date: 8/3/26
Time: 3:26 PM
Method: Grab*

Sample Final Analysis

*Date: 8/6/26
Time: 11:00 AM
Analyst: AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	8/4/26	10:40 AM	MD	SM 9222G
Total coliforms:	0/100mls	2/100mls	8/4/26	10:40 AM	MD	SM 9222B
Standard plate count:	0/ml	200/ml	8/3/26	6:15 PM	AS	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	8/3/26	3:26 PM	MM	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	8/3/26	3:26 PM	MM	DPD
Turbidity:	1 NTU	1 - 2 NTU	8/3/26	3:26 PM	MM	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor