



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 2

Lab# 2726

Customer

American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: Felson Apts

Date: 5/27/26

Address: 8000 Brandt Dr.
Cranberry, PA 16066

Time: 1:48 PM

Method: Grab

Sample Final Analysis

Matrix: Recreational Water

Date: 5/29/26

Source Type: Pool

Time: 10:30 AM

Analyst: AS

Accredited Analysis	Results	Reporting limit	Incubation Date/Time	Analyst	Method
Escherichia Coli:	Absent	Absent	5/28/26 10:00 AM	SL	SM 9222G
Total coliforms:	0/100mls	2/100mls	5/28/26 10:00 AM	SL	SM 9222B
Standard plate count:	0/ml	200/ml	5/27/26 4:45 PM	AH	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time	Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	5/27/26 1:48 PM	SL	DPD
Chlorine:	3.0 mg/l	1.0 - 5.0 mg/l	5/27/26 1:48 PM	SL	DPD
Turbidity:	1 NTU	1 - 2 NTU	5/27/26 1:48 PM	SL	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)