



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

S-15

Lab# 2541

Customer

Facility Name: Valley Brook Country Club

Address: 4 Hidden Valley Road
Canonsburg, PA 15317

Matrix: Recreational Water

Source Type: Deep End

Sample Collection

Date: 7/15/26

Time: 9:15 AM

Method: Grab

Sample Final Analysis

Date: 7/18/26

Time: 10:30 AM

Analyst: #REF!

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	7/16/26	10:00 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	7/16/26	10:00 AM	AH	SM 9222B
Standard plate count:	0/ml	200/ml	7/15/26	4:30 PM	SL	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	7/15/26	9:15 AM	JB	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	7/15/26	9:15 AM	JB	DPD
Turbidity:	1 NTU	1 - 2 NTU	7/15/26	9:15 AM	JB	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)