



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 2

Lab# 2226

Customer *American Pools Management*
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Glencannon* *Date:* *9/1/26*
Address: *207 Driftwood Road* *Time:* *11:05 AM*
Canonsburg, PA 15317 *Method:* *Grab*

Sample Final Analysis

Matrix: *Recreational Water* *Date:* *9/4/26*
Source Type: *Wading Pool* *Time:* *10:00 AM*
Analyst: *AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	9/2/26	9:30 AM	AS	SM 9222G
Total coliforms:	0/100mls	2/100mls	9/2/26	9:30 AM	AS	SM 9222B
Standard plate count:	0/ml	200/ml	9/1/26	2:46 PM	AH	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.4 SU	7.2 - 7.8 SU	9/1/26	11:05 AM	JM	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	9/1/26	11:05 AM	JM	DPD
Turbidity:	1 NTU	1 - 2 NTU	9/1/26	11:05 AM	JM	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)