



Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

W-2

Lab# 411

Customer

Facility Name: *Fairfield Inn Airport*
Address: *1004 Sutherland Dr*
Pittsburgh, PA 15205

Sample Collection

Date: *9/14/26*
Time: *1:12 PM*
Method: *Grab*

Sample Final Analysis

Date: *9/17/26*
Time: *10:30 AM*
Analyst: *JC*

Matrix: *Recreational Water*

Source Type: *Spa*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	9/15/26	10:10 AM	AH	SM 9222G
Total coliforms:	0/100mls	2/100mls	9/15/26	10:10 AM	AH	SM 9222B
Standard plate count:	5700/ml	200/ml	9/14/26	5:17 PM	JC	SM 9215B
Additional Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Fecal Streptococcus	0/100mls	2/100mls	9/15/26	12:12 PM	AH	SM 9230C
Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	8.0 SU	7.2 - 7.8 SU	9/14/26	1:12 PM	MH	DPD
Chlorine:	0.0 mg/l	1.0 - 5.0 mg/l	9/14/26	1:12 PM	MH	DPD
Turbidity:	1 NTU	1 - 2 NTU	9/14/26	1:12 PM	MH	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith, Lead Supervisor