Dream Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665

Laboratory Analysis Report

Lab ID No. 02-04041

C-11

Lab# 2535

Customer		***Sample Collection***	
Facility Name:	*Trimont*	*Date:*	*8/31/26*
		Time:	10:35 AM
Address:	*1 Trimont Ln.*	*Method:*	*Grab*
	Pittsburgh, PA 15211		
		Sample Final Analysis	
Matrix:	*Recreational Water*	*Date:*	*9/3/26*
		Time:	*11:00 AM*
Source Type:	*Pool*	*Analyst:*	*AS*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	9/1/26	10:30 AM	AS	SM 9222G
Total coliforms:	0/100mls	2/100mls	9/1/26	10:30 AM	AS	SM 9222B
Standard plate count:	20/ml	200/ml	8/31/26	4:12 PM	AH	SM 9215B

Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.6 SU	7.2 - 7.8 SU	8/31/26	10:35 AM	JT	DPD
Chlorine:	1.0 mg/l	1.0 - 5.0 mg/l	8/31/26	10:35 AM	JT	DPD
Turbidity:	1 NTU	1 - 2 NTU	8/31/26	10:35 AM	JT	Visual

Sample comments

(When exceeding reporting limit pool or spa is unfit)

Andre Smith

Andre Smith, Lead Supervisor