Dreams Pools and Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041
PPS
Lab# 004

Customer		Sample Collection	
Facility Name:	Allderdice H.S.	Date:	10/14/26
		Time:	10:35 AM
Address:	2409 Shady Ave. Pittsburgh, PA 15217	Method:	Grab
		Sample Final Analysis	
Matrix:	Recreational Water	Date:	10/16/26
		Time:	5:30 PM
Source Type:	Pool Shallow	Analyst:	JC

Accredited Analysis	Results	Rating	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	A	10/14/26	5:00 PM	AS	SM 9222G
Total coliforms:	0/100mls	A	10/14/26	5:00 PM	AS	SM 9222B
Standard plate count:	0/ml	A	10/14/26	4:15 PM	AS	SM 9215B

Field Analysis	Results	Rating	Date/Time		Analyst	Method
pH:	7.6 SU	A	10/14/26	10:35 AM	MM	DPD
Chlorine:	2.0 mg/l	B	10/14/26	10:35 AM	MM	DPD
Turbidity:	1 NTU	A	10/14/26	10:35 AM	MM	Visual

Sample comments

Andre Smith

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)