



Dream Pools And Spas
1105 Washington Blvd
Pittsburgh, Pennsylvania 15206
(412) 661- 7665
Laboratory Analysis Report

Lab ID No. 02-04041

APM 1

Lab# 2819

Customer

American Pools Management
3261 Babcock Blvd.
Pittsburgh, PA 15237

Sample Collection

Facility Name: *Beaver Creek*

Date: *8/17/26*

Time: *12:05 PM*

Address: *500 Center Grange Rd.*
Monaca, PA 15061

Method: *Grab*

Sample Final Analysis

Matrix: *Recreational Water*

Date: *8/21/26*

Time: *12:00 PM*

Source Type: *Pool*

Analyst: *1/0/00*

Accredited Analysis	Results	Reporting limit	Incubation Date/Time		Analyst	Method
Escherichia Coli:	Absent	Absent	8/18/26	11:30 AM	JC	SM 9222G
Total coliforms:	1/100mls	2/100mls	8/18/26	11:30 AM	JC	SM 9222B
Standard plate count:	5700/ml	200/ml	8/17/26	6:45 PM	SL	SM 9215B
Field Analysis	Results	Reporting limit	Date/Time		Analyst	Method
pH:	7.2 SU	7.2 - 7.8 SU	8/17/26	12:05 PM	AMH	DPD
Chlorine:	0.0 mg/l	1.0 - 5.0 mg/l	8/17/26	12:05 PM	AMH	DPD
Turbidity:	1 NTU	1 - 2 NTU	8/17/26	12:05 PM	AMH	Visual

Sample comments

Andre Smith, Lead Supervisor

(When exceeding reporting limit pool or spa is unfit)