

EXPERIMENT - 1

REGISTER NUMBER : 23MIS0142

NAME : BARATH D

BAD DESIGN -1 WATER DISPENSER

DESCRIPTION:

A water dispenser must have the proper indication of temperature of water (HOT/COLD).It makes it difficult for the users to identify the required temperature.

SOURCE OF PHOTOGRAPH:



PLACE:

VIT – SJT

Reason why the design is bad:

- No indication of temperature
- Difficult for new students

Suggested Improvement:

- Use proper labels

BAD DESIGN -2 STAIRCASE

DESCRIPTION:

The way of using the staircases must be properly labelled correctly to ease the use of staircase. This makes it easier and reduces the disturbances caused by the wrong use of it.

SOURCE OF PHOTOGRAPH:



PLACE:

VIT – SJT

Reason why the design is bad:

- No labelling of correct usage
- Difficult for many students

Suggested Improvement:


- Usage of proper labels

BAD DESIGN -3 NOTICE BOARDS

DESCRIPTION:

The notice boards can be maintained and aligned properly which makes it easy for students to view the new information and events in college.

SOURCE OF PHOTOGRAPH:



PLACE:

VIT – SJT

Reason why the design is bad:

- The boards are very clumpy
- Difficult to view the recent updates and events

Suggested Improvement:

- Make neat alignments of the boards
- Use separate columns for different