

Report No.:D0095707649

# Inspection Report

This report is created by

**LAUNCH**

## Vehicle Information

**VIN:** WP0AD2A74EL044881**Vehicle manufacturer/model:** Porsche/Panamera S Hybrid**Year of manufacture:** 2014**Odometer:** 174372**Vehicle Software Version:** V24.52**Repair State:** 1

## Inspection Organization

**Name:** Bavarian Dismantlers**Address:** 7091 South Coolidge Court**Contact Number:** ☎ 3128139067**SN:** 979624004768**Time and date of inspection:** 2025-11-10 11:07:46

## Inspection Result

**There are 2 issues for Power system:**

- 1.Bank 2 Secondary-Air System Malfunction
- 2.Bank 1 Secondary-Air System, Flow Below Limit

**There are 2 issues for Safety and Security system:**

- 1.No Communication With Air Conditioner Regulator
- 2.Function Restriction Due To Fault In PSM

**There are 11 issues for Vehicle body system:**

- 1.Function Restriction Due To Missing Message
- 2.No Communication With TPM Control Unit
- 3.No Communication With PASM Control Unit
- 4.No Communication With TPM Control Unit
- 5.Check High-Voltage Battery Control Unit Fault Memory Content
- 6.No Communication With PASM Control Unit
- 7.Check PASM Control Unit Fault Memory Content
- 8.Communication With Slide/Tilt Roof (Rear 1)
- 9.No Communication With TPM Control Unit
- 10.No Communication With TPM Control Unit
- 11.Key Battery Flat

**There are 1 issues for Infotainment system:**

- 1.Satellite Antenna, Open Circuit

---

**Inspections are normal for Power system**

- 1.Selector Lever
- 2.Transmission Control Module (TCM/PDK)
- 3.High-Voltage Battery

**Inspections are normal for Safety and Security system**

- 1.Electrical Parking Brake (EPB)
- 2.Reversing Camera
- 3.Steering Wheel Electronic
- 4.Park Assist
- 5.Supplemental Inflatable Restraint System (SRS)
- 6.Lane Change Assist

**Inspections are normal for Vehicle body system**

- 1.High-Voltage Charger
- 2.Passenger's Door
- 3.Additional Instrument:Watch
- 4.Driver's Door
- 5.Driver-Side Seat Memory
- 6.High-Voltage Power Electronics
- 7.Passenger-Side Seat Memory
- 8.Power Tail Gate (PTG)
- 9.External Amplifier
- 10.Rear Right Door
- 11.Rear Left Door

---

**Professional Report**

---

High-Voltage Charger	Normal	▼
----------------------	--------	---

Electronic Stabily Program (ESP/PSM)	Abnormal	1	^
--------------------------------------	----------	---	---

**DTC Qty (1)**

C12019	...	Inactive
--------	-----	----------

Passenger's Door	Normal	▼
------------------	--------	---

Engine Control Module (ECM/DME)	Abnormal	2	^
---------------------------------	----------	---	---

**DTC Qty (2)**

P049200	...	No fault status available
---------	-----	---------------------------

P049100	...
---------	-----

No fault status available

Electrical Parking Brake (EPB) Normal 


Additional Instrument:Watch Normal 

A/C Compressor Abnormal 1 

DTC Qty (1)

U111100 ...

Inactive

Instrument cluster (IC) Abnormal 1 

DTC Qty (1)

C12015 ...

Active

Reversing Camera Normal 

Headlight (Central) Abnormal 1 

DTC Qty (1)

C1200C ...

Inactive

Driver's Door Normal 

Driver-Side Seat Memory Normal 

High-Voltage Power Electronics Normal 

Selector Lever Normal 

Electronic Power Steering (EPS) Abnormal 1 

DTC Qty (1)

D00000 ...

Inactive

Steering Wheel Electronic Normal 

Transmission Control Module (TCM/PDK)		Normal	▼
Passenger-Side Seat Memory		Normal	▼
GATEWAY		Abnormal	2 ^
DTC Qty (2)			
C12015	...	Active	
C120A9	...	Inactive	
Power Tail Gate (PTG)		Normal	▼
Air Conditioning (AC)		Abnormal	2 ^
DTC Qty (2)			
C1200C	...	Inactive	
C1208A	...	Inactive	
External Amplifier		Normal	▼
Park Assist		Normal	▼
Rear Right Door		Normal	▼
Rear Left Door		Normal	▼
Rear-End Electronics		Abnormal	2 ^
DTC Qty (2)			
C13314	...	Active	
C12015	...	Active	
High-Voltage Battery		Normal	▼

Front-End Electronics

Abnormal 2 ^

DTC Qty (2)

C12015	...	Active
881202	...	Active

Supplemental Inflatable Restraint System (SRS)

Normal v

Lane Change Assist

Normal v

PCM/CDR (Communication Management/Cd Radio)

Abnormal 1 ^

DTC Qty (1)

008006	...	No fault symptom available
--------	-----	----------------------------

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.