

Report No.:D0095778250

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: WP0AD2A74EL044881**Vehicle manufacturer/model:** Porsche/Panamera S Hybrid**Year of manufacture:** 2014**Odometer:** 174372**Vehicle Software Version:** V24.52**Repair State:** 1

Inspection Organization

Name: Bavarian Dismantlers**Address:** 7091 South Coolidge Court**Contact Number:** ☎ 3128139067**SN:** 979624004768**Time and date of inspection:** 2025-11-11 11:40:08

Inspection Result

There are 7 issues for Vehicle body system:

- 1.No Communication With PASM Control Unit
- 2.No Communication With TPM Control Unit
- 3.No Communication With PASM Control Unit
- 4.Check PASM Control Unit Fault Memory Content
- 5.Communication With Slide/Tilt Roof (Rear 1)
- 6.No Communication With TPM Control Unit
- 7.No Communication With TPM Control Unit

Inspections are normal for Power system

- 1.Engine Control Module (ECM/DME)
- 2.Selector Lever
- 3.Transmission Control Module (TCM/PDK)
- 4.High-Voltage Battery

Inspections are normal for Safety and Security system

- 1.Electronic Stability Program (ESP/PSM)
- 2.Electrical Parking Brake (EPB)
- 3.Reversing Camera
- 4.Electronic Power Steering (EPS)
- 5.Steering Wheel Electronic

- 6.Park Assist
- 7.Supplemental Inflatable Restraint System (SRS)
- 8.Lane Change Assist

Inspections are normal for Vehicle body system

- 1.High-Voltage Charger
- 2.Passenger's Door
- 3.Additional Instrument:Watch
- 4.A/C Compressor
- 5.Instrument cluster (IC)
- 6.Driver's Door
- 7.Driver-Side Seat Memory
- 8.High-Voltage Power Electronics
- 9.Passenger-Side Seat Memory
- 10.Power Tail Gate (PTG)
- 11.External Amplifier
- 12.Rear Right Door
- 13.Rear Left Door

Inspections are normal for Infotainment system

- 1.PCM/CDR (Communication Management/Cd Radio)

Professional Report

| | | |
|---------------------------------------|----------|-----|
| High-Voltage Charger | Normal | ▼ |
| Electronic Stabilty Program (ESP/PSM) | Normal | ▼ |
| Passenger's Door | Normal | ▼ |
| Engine Control Module (ECM/DME) | Normal | ▼ |
| Electrical Parking Brake (EPB) | Normal | ▼ |
| Additional Instrument:Watch | Normal | ▼ |
| A/C Compressor | Normal | ▼ |
| Instrument cluster (IC) | Normal | ▼ |
| Reversing Camera | Normal | ▼ |
| Headlight (Central) | Abnormal | 1 ^ |

DTC Qty (1)

C1200C

...

Inactive

Driver's Door

Normal ▾

Driver-Side Seat Memory

Normal ▾

High-Voltage Power Electronics

Normal ▾

Selector Lever

Normal ▾

Electronic Power Steering (EPS)

Normal ▾

Steering Wheel Electronic

Normal ▾

Transmission Control Module (TCM/PDK)

Normal ▾

Passenger-Side Seat Memory

Normal ▾

GATEWAY

Abnormal 1 ^

DTC Qty (1)

C12015

...

Active

Power Tail Gate (PTG)

Normal ▾

Air Conditioning (AC)

Abnormal 2 ^

DTC Qty (2)

C1200C

...

Inactive

C1208A

...

Inactive

External Amplifier

Normal ▾

Park Assist

Normal ▾

Rear Right Door

Normal ▾

| | | | |
|--|-----|----------|-----|
| Rear Left Door | | Normal | ▼ |
| Rear-End Electronics | | Abnormal | 2 ^ |
| DTC Qty (2) | | | |
| C13314 | ... | Active | |
| C12015 | ... | Active | |
| High-Voltage Battery | | Normal | ▼ |
| Front-End Electronics | | Abnormal | 1 ^ |
| DTC Qty (1) | | | |
| C12015 | ... | Active | |
| Supplemental Inflatable Restraint System (SRS) | | Normal | ▼ |
| Lane Change Assist | | Normal | ▼ |
| PCM/CDR (Communication Management/Cd Radio) | | Normal | ▼ |

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.