



**PT. ELCONINDO TECHNIC SOLUSI**

Electrical, Instrumentation, Mechanical,  
Civil Work and General Supply



## PURCHASE ORDER

To : **PT. NAJWA JAYA SUKSES**

Jl. Raya Salira, Kp. Pengoreng RT-06/02

Ds. Mangunreja, Kec. Puloampel

Kab. Serang - Banten

Phone No. : 081911231438/085219691708

Attn. : **Mr. Arifudin/Direktur**

PO/WO NO. : 007/PO-NJS/V/23/R1

Date : 28 May 2023

Revision : 01

Delivery Time : ASAP

Franco : PT. SAU Factory

Job Code : JC-031/23

Your Ref. No. : -

NO.	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
1	Jasa Install Instrument Waste Water at VCM Plant ( See Attachment )  Note : Harga Sudah Termasuk Assist Commissioning, TKBT, LSM, Etc	1	Lot	90.000.000,00	90.000.000,00

1. Harga Sudah Termasuk PPh-23

2. Pembayaran : 45 Hari Setelah BAP dan Invoice diterima dengan Baik.

Sub Total	90.000.000,00
Discount	-
Total	<b>90.000.000,00</b>
PPN ( 11% )	9.900.000,00
Total + PPN	<b>99.900.000,00</b>

Confirmed by Vendor

**PT. Elconindo Technic Solusi**

Prepared by	Checked by	Approved by
Procurement	Manager	Director

By

Please Confirm by signing, stamp, stamp & return to us within two (2) days of receipt date PO.



**GENERAL TERM & CONDITION**  
**PO NO. 007/PO-NJS/V/23**  
**( Jasa Install Instrument Waste Water at VCM Plant )**

1. PT. Najwa harus mengikuti prosedur dan peraturan keselamatan kerja yang berlaku di PT. SAU
2. PT. Najwa wajib menggunakan PPE yang masih layak pakai dan sesuai yang disyaratkan oleh pekerjaan.
3. PT. Najwa harus mengikuti safety briefing/safety induction untuk mendapatkan ID Card dan melakukan persiapan sebelum bekerja.
4. PT. Najwa wajib memelihara lingkungan kerja ( melakukan house keeping ) setiap selesai bekerja.
5. PT. Najwa bertanggung jawab atas peralatan yang dipinjamkan dari PT. ETS, dan akan dikenakan ganti rugi untuk setiap kerusakan.
6. PT. Najwa harus memenuhi schedule pekerjaan ( tepat waktu ) dalam menyelesaikan pekerjaan, dan akan dikenakan sanksi ( denda ) sebesar 1% perhari atas keterlambatannya.
7. PT. Najwa bertanggung jawab atas semua kerugian atau kerusakan yang disebabkan oleh kelalaian tenaga kerjanya.
8. Pekerjaan ini adalah Lump Sum Work ( tidak ada kerja tambah / additional cost ) dalam pelaksanaan pekerjaan

PT. Elconindo Technic Solusi



Benni Chaldir  
Project Mng

Accepted by :

PT. Najwa Jaya Sukses

Arifuddin  
Direktur