

view_frames Result

Recorded at time: 1784521487.7819204

base_footprint

Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0

base_link

Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0

chassis

Broadcaster: default_authority
Average rate: 20.215
Buffer length: 4.65
Most recent transform: 35.8
Oldest transform: 31.15

drivewhl_l_link

Broadcaster: default_authority
Average rate: 20.215
Buffer length: 4.65
Most recent transform: 35.8
Oldest transform: 31.15

drivewhl_r_link

Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0

imu_link

Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0

lidar_link