



CARROBAAR DRIVE

PREMIUM INSPECTION REPORT



Maruti WagonR

VARIANT: VXi • REG: GJ23CH4369

88%

EXCELLENT
VEHICLE HEALTH

✓ PASSED

112

⚠ MINOR DEFECTS

4

🚫 MAJOR DEFECTS

0

📷 PHOTOS

16

VEHICLE INFORMATION

Make & Model	Variant / Year
Maruti WagonR	Vxi / 2026
Fuel Type	Transmission
CNG	Manual
Chassis Number (VIN)	
ABCD	
Odometer Reading	Exterior Color
8 KM	White

INSPECTION INFORMATION

Inspection ID	Inspector
1782567867466	Bhavya (Certified)
Inspection Date	Inspection Location
27 Jun '26	Janta Chokdi, Anand
Dealership Partner	
Amar Cars	
Report Status	Dossier Version
COMPLETED	v2.5 Premium

FINAL RECOMMENDATION

ACCEPT AFTER MINOR RECTIFICATION OF COSMETIC/MINOR FAULTS

Suitable for immediate delivery. No defects or malfunctions found.



DOCUMENT DIRECTORY

INTERACTIVE REPORT INDEX

PART I: REPORT METRICS & OVERVIEW

1. Inspection Dashboard	Page 2
2. Technical Specifications	Page 2
3. Mandatory Photo Registry - Part 1	Page 3
4. Mandatory Photo Registry - Part 2	Page 4

PART II: DETAILED SYSTEM INSPECTIONS

1. Documents Verification	✓ CHECKED
2. Body Panels	✓ CHECKED
3. Glass	✓ CHECKED
4. Lighting	✓ CHECKED
5. Wheels	✓ CHECKED
6. Tyres	✓ CHECKED
7. Underbody	✓ CHECKED
8. Exterior Trim	✓ CHECKED
9. Dashboard & Instrument Cluster	✓ CHECKED
10. Steering & Controls	✓ CHECKED
11. Seats & Upholstery	✓ CHECKED
12. Door Trims & Panels	✓ CHECKED
13. Roof & Headliner	✓ CHECKED
14. Infotainment System	✓ CHECKED
15. HVAC System	✓ CHECKED
16. Mirrors	✓ CHECKED
17. Feature Verification	✓ CHECKED
18. EV Systems	✓ CHECKED
19. Accessories	✓ CHECKED
20. Road Test	✓ CHECKED

PART III: EVIDENCE GALLERY & VERIFICATION

5. Defect Evidence Gallery	Appendix A
6. Signatures & Verification	Appendix B



INSPECTION DASHBOARD

QUALITY SCORE



EXCELLENT
Overall Verdict

INSPECTION SUMMARY

The pre-delivery evaluation checked 205 components. Total passed rate stands at 55% with 4 total faults.

* Note: The Quality Score (88%) is the health rating of the inspected systems (with deductions only for faults found), whereas the Pass Rate (55%) represents the percentage of all 205 checkpoints in the template that have been verified and marked as cleared.

FAULT STATISTICS

Cosmetic / Minor concerns: 4 faults. Safety / Major mechanical concerns: 0 faults.

VEHICLE STRENGTHS

The vehicle is in good general health with no structural or electronic malfunctions detected.

MAJOR / SAFETY CONCERNS

No safety-critical concerns found, but minor cosmetic rectifications are recommended.



INSPECTOR RECOMMENDATIONS

Suitable for immediate delivery. No defects or malfunctions found.

CHECKPOINT CATEGORIES

Body Panels

13 Checkpoints

1 FAULTS

Wheels

5 Checkpoints

1 FAULTS

Exterior Trim

12 Checkpoints

2 FAULTS

Door Trims & Panels

10 Checkpoints

✓ CLEARED

Documents Verification

7 Checkpoints

✓ CLEARED

Glass

10 Checkpoints

✓ CLEARED

VEHICLE SPECIFICATIONS

MAKE & MODEL

Maruti WagonR

VARIANT / TRIM

Vxi

YEAR / MONTH

January 2026

VIN / CHASSIS NUMBER

ABCD

ODOMETER READING

8 KM

ENGINE NUMBER

A1235BEI2B0

REGISTRATION NUMBER

GJ23CH4369

POWERTRAIN / TRANSMISSION

CNG • Manual

MANDATORY PHOTO REGISTRY - PART 1

VEHICLE EXTERIOR & COMPLIANCE CHECK



FRONT VIEW




REAR VIEW



LEFT SIDE



RIGHT SIDE



VIN



ODOMETER

MANDATORY PHOTO REGISTRY - PART 2

POWERTRAIN, ACCESSORIES & UNDERBODY VIEWS



ENGINE BAY / FRUNK




KEY SET



TOOLKIT



SPARE WHEEL



CHARGING PORT / FUEL FILLING CAP



UNDERBODY VIEW



DOCUMENTS VERIFICATION

SECTION TITLE

DOCUMENTS VERIFICATION

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

7

PASSED

7

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Invoice	N/I	Not Inspected		No	—
2	Insurance	N/I	Not Inspected		No	—
3	RC	N/I	Not Inspected		No	—
4	Warranty Booklet	N/I	Not Inspected		No	—
5	Service Book	N/I	Not Inspected		No	—
6	PUC	N/I	Not Inspected		No	—
7	Other Documents	N/I	Not Inspected		No	—

Section Documents Verification completed successfully • Total Checkpoints: 7 • Passed: 7 • Minor: 0 • Major: 0 • Critical: 0

BODY PANELS

SECTION TITLE

BODY PANELS

COMPLETION

100% SECURE

PASS RATE SCORE

92%

CHECKPOINTS

13

PASSED

12

MINOR / MAJOR / CRITICAL

1 / 0 / 0

PHOTOS

1 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Front Bumper	PASS			No	✓
2	Hood	PASS			No	✓
3	Front Fender LH	PASS			No	✓
4	Front Fender RH	PASS			No	✓
5	Front Door LH	PASS			No	✓
6	Front Door RH	PASS			No	✓
7	Rear Door LH	PASS			No	✓
8	Rear Door RH	PASS			No	✓
9	Quarter Panel LH	PASS			No	✓
10	Quarter Panel RH	PASS			No	✓
11	Tailgate / Boot Lid	PASS			No	✓
12	Roof	MINOR	Scratch observed on Roof.	Cosmetic rectification before delivery.	Yes	⚠
13	Rear Bumper	PASS			No	✓

DEFECT CARD: ROOF

MINOR ISSUEEst: ₹TBD

Observation: Scratch observed on Roof.

Recommendation: Cosmetic rectification before delivery.



Section **Body Panels** completed successfully • Total Checkpoints: 13 • Passed: 12 • Minor: 1 • Major: 0 • Critical: 0

GLASS

SECTION TITLE	COMPLETION		PASS RATE SCORE
GLASS	100% SECURE		100%
CHECKPOINTS 10	PASSED 10	MINOR / MAJOR / CRITICAL 0 / 0 / 0	PHOTOS 0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Front Windshield	PASS			No	✓
2	Rear Windshield	PASS			No	✓
3	Front Glass LH	PASS			No	✓
4	Front Glass RH	PASS			No	✓
5	Rear Glass LH	PASS			No	✓
6	Rear Glass RH	PASS			No	✓
7	Quarter Glass LH	N/A	Not Applicable		No	—
8	Quarter Glass RH	N/A	Not Applicable		No	—
9	Sunroof	N/A	Not Applicable		No	—
10	Panoramic Roof	N/A	Not Applicable		No	—



Section **Glass** completed successfully • Total Checkpoints: 10 • Passed: 10 • Minor: 0 • Major: 0 • Critical: 0

LIGHTING

SECTION TITLE
LIGHTING

COMPLETION
100% SECURE

PASS RATE SCORE
100%

CHECKPOINTS
15

PASSED
15

MINOR / MAJOR / CRITICAL
0 / 0 / 0

PHOTOS
0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Headlamp LH	PASS			No	✓
2	Headlamp RH	PASS			No	✓
3	DRL	N/A	Not Applicable		No	—
4	Indicator LH	PASS			No	✓
5	Indicator RH	PASS			No	✓
6	Fog Lamp LH	N/A	Not Applicable		No	—
7	Fog Lamp RH	N/A	Not Applicable		No	—
8	Tail Lamp LH	PASS			No	✓
9	Tail Lamp RH	PASS			No	✓
10	Connected Tail Lamp	N/A	Not Applicable		No	—
11	Reverse Lamp	PASS			No	✓
12	Number Plate Lamp	PASS			No	✓
13	Puddle Lamp	N/A	Not Applicable		No	—
14	Cornering Lamp	N/A	Not Applicable		No	—
15	Rear Fog Lamp	N/A	Not Applicable		No	—

Section **Lighting** completed successfully • Total Checkpoints: 15 • Passed: 15 • Minor: 0 • Major: 0 • Critical: 0

WHEELS

SECTION TITLE
WHEELS

COMPLETION
100% SECURE

PASS RATE SCORE
80%

CHECKPOINTS
5

PASSED
4

MINOR / MAJOR / CRITICAL
1 / 0 / 0

PHOTOS
1 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Wheel FL	PASS			No	✓
2	Wheel FR	PASS			No	✓
3	Wheel RL	MINOR	Wheel design differs from specified vehicle variant on Wheel RL.	Dealer clarification required.	Yes	⚠
4	Wheel RR	PASS			No	✓
5	Spare Wheel	PASS			No	✓

⚠ DEFECT CARD: WHEEL RL

MINOR ISSUE Est: ₹TBD

Observation: Wheel design differs from specified vehicle variant on Wheel RL.

Recommendation: Dealer clarification required.



Section **Wheels** completed successfully • Total Checkpoints: 5 • Passed: 4 • Minor: 1 • Major: 0 • Critical: 0

TYRES

SECTION TITLE TYRES	COMPLETION 100% SECURE	PASS RATE SCORE 100%
CHECKPOINTS 6	PASSED 6	MINOR / MAJOR / CRITICAL 0 / 0 / 0
		PHOTOS 0 Photos



NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Tyre FL	PASS			No	✓
2	Tyre FR	PASS			No	✓
3	Tyre RL	PASS			No	✓
4	Tyre RR	PASS			No	✓
5	Spare Tyre	PASS			No	✓
6	TPMS	PASS			No	✓

TYRE SPECIFICATIONS & PARAMETER DETAILS

POSITION	BRAND	SIZE	MFG WEEK/YEAR	TREAD DEPTH	OEM MATCH	PRESSURE	ROTATION
Tyre FL	Ceat	185/55 R15	Wk 48/2025	8.3 mm	Yes	33 PSI	Correct
Tyre FR	Ceat	185/55 R15	Wk 48/2025	8.4 mm	Yes	33 PSI	Correct
Tyre RL	Ceat	185/55 R15	Wk 48/2025	8.3 mm	Yes	34 PSI	Correct
Tyre RR	Ceat	185/55 R15	Wk 48/2025	8.4 mm	Yes	32 PSI	Correct
Spare Tyre	Ceat	185/55 R15	—	—	—	—	—
TPMS	—	—	—	—	—	—	—

Section **Tyres** completed successfully • Total Checkpoints: 6 • Passed: 6 • Minor: 0 • Major: 0 • Critical: 0

UNDERBODY

SECTION TITLE
UNDERBODY

COMPLETION
100% SECURE

PASS RATE SCORE
100%

CHECKPOINTS
9

PASSED
9

MINOR / MAJOR / CRITICAL
0 / 0 / 0

PHOTOS
0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Front Underbody	PASS			No	✓
2	Rear Underbody	PASS			No	✓
3	Side Sills	PASS			No	✓
4	Suspension Area	PASS			No	✓
5	Exhaust Area	PASS			No	✓
6	Battery Protection Shield	N/A	Not Applicable		No	—
7	Floor Pan	PASS			No	✓
8	Engine Cover	N/A	Not Applicable		No	—
9	Underbody Coating	N/A	Not Applicable		No	—

Section **Underbody** completed successfully • Total Checkpoints: 9 • Passed: 9 • Minor: 0 • Major: 0 • Critical: 0



EXTERIOR TRIM

SECTION TITLE	COMPLETION		PASS RATE SCORE
EXTERIOR TRIM	100% SECURE		83%
CHECKPOINTS	PASSED	MINOR / MAJOR / CRITICAL	PHOTOS
12	10	2 / 0 / 0	1 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	ORVM LH	PASS			No	✓
2	ORVM RH	PASS			No	✓
3	Door Handles	MINOR	Improper fitment of trim on Door Handles.	Dealer rectification before delivery.	Yes	⚠
4	Roof Rails	PASS			No	✓
5	Badges	PASS			No	✓
6	Claddings	N/A	Not Applicable		No	—
7	Chrome Trim	PASS			No	✓
8	Weather Strips	PASS			No	✓
9	Mud Flaps	N/A	Not Applicable		No	—
10	Antenna	PASS			No	✓
11	Wiper Arms	MINOR	Wiper arm leaving marks on windshield while operation	Dealer rectification before delivery.	No	⚠
12	Wiper Function Check	PASS			No	✓



 DEFECT CARD: DOOR HANDLES

MINOR ISSUE Est: ₹TBD

Observation: Improper fitment of trim on Door Handles.

Recommendation: Dealer rectification before delivery.



 DEFECT CARD: WIPER ARMS

MINOR ISSUE Est: ₹TBD

Observation: Wiper arm leaving marks on windshield while operation

Recommendation: Dealer rectification before delivery.



PHOTO PLACEHOLDER



Section **Exterior Trim** completed successfully • Total Checkpoints: 12 • Passed: 10 • Minor: 2 • Major: 0 • Critical: 0

DASHBOARD & INSTRUMENT CLUSTER

SECTION TITLE

DASHBOARD & INSTRUMENT CLUSTER

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

10

PASSED

10

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Dashboard Assembly	PASS			No	✓
2	Instrument Cluster	PASS			No	✓
3	Warning Lamps	PASS			No	✓
4	MID Display	PASS			No	✓
5	Speedometer	PASS			No	✓
6	Tachometer	PASS			No	✓
7	Fuel Gauge	PASS			No	✓
8	Range Display	N/A	Not Applicable		No	—
9	EV Information Display	N/A	Not Applicable		No	—
10	Ambient Lighting Controls	N/A	Not Applicable		No	—

Section **Dashboard & Instrument Cluster** completed successfully • Total Checkpoints: 10 • Passed: 10 • Minor: 0 • Major: 0 • Critical: 0

STEERING & CONTROLS

SECTION TITLE

STEERING & CONTROLS

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

13

PASSED

13

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos



NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Steering Wheel	PASS			No	✓
2	Steering Adjustment	PASS			No	✓
3	Steering Buttons	N/A	Not Applicable		No	—
4	Horn	PASS			No	✓
5	Cruise Controls	N/A	Not Applicable		No	—
6	ADAS Controls	N/A	Not Applicable		No	—
7	Paddle Shifters	N/A	Not Applicable		No	—
8	Drive Mode Controls	N/A	Not Applicable		No	—
9	Regeneration Controls	N/A	Not Applicable		No	—
10	Indicator Stalk	PASS			No	✓
11	Wiper Stalk	PASS			No	✓
12	Ignition Switch	PASS			No	✓
13	Push Button Start	N/A	Not Applicable		No	—

Section **Steering & Controls** completed successfully • Total Checkpoints: 13 • Passed: 13 • Minor: 0 • Major: 0 • Critical: 0

SEATS & UPHOLSTERY

SECTION TITLE	COMPLETION	PASS RATE SCORE
SEATS & UPHOLSTERY	100% SECURE	100%
CHECKPOINTS 14	PASSED 14	MINOR / MAJOR / CRITICAL 0 / 0 / 0
		PHOTOS 0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Driver Seat	PASS			No	✓
2	Passenger Seat	PASS			No	✓
3	Rear Seat	PASS			No	✓
4	Third Row Seat	PASS			No	✓
5	Seat Belts	PASS			No	✓
6	Headrests	N/A	Not Applicable		No	—
7	Seat Adjustment	PASS			No	✓
8	Seat Recline	PASS			No	✓
9	Lumbar Support	N/A	Not Applicable		No	—
10	Ventilated Seats	N/A	Not Applicable		No	—
11	Heated Seats	N/A	Not Applicable		No	—
12	Seat Memory Function	N/A	Not Applicable		No	—
13	Armrests	N/A	Not Applicable		No	—
14	Seat Fabric / Leather	N/A	Not Applicable		No	—



Section **Seats & Upholstery** completed successfully • Total Checkpoints: 14 • Passed: 14 • Minor: 0 • Major: 0 • Critical: 0

DOOR TRIMS & PANELS

SECTION TITLE

DOOR TRIMS & PANELS

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

10

PASSED

10

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Front Door LH	PASS			No	✓
2	Front Door RH	PASS			No	✓
3	Rear Door LH	PASS			No	✓
4	Rear Door RH	PASS			No	✓
5	Door Handles	N/I	Not Inspected		No	—
6	Door Pockets	PASS			No	✓
7	Door Padding	PASS			No	✓
8	Armrests	N/A	Not Applicable		No	—
9	Window Switches	PASS			No	✓
10	Door Seals	PASS			No	✓

Section **Door Trims & Panels** completed successfully • Total Checkpoints: 10 • Passed: 10 • Minor: 0 • Major: 0 • Critical: 0

ROOF & HEADLINER

SECTION TITLE

ROOF & HEADLINER

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

8

PASSED

8

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Roof Lining	PASS			No	✓
2	Sun Visors	PASS			No	✓
3	Grab Handles	PASS			No	✓
4	Interior Trim	PASS			No	✓
5	Sunroof	N/A	Not Applicable		No	—
6	Panoramic Roof	N/A	Not Applicable		No	—
7	Sunroof Shade	N/A	Not Applicable		No	—
8	Roof Lighting	N/A	Not Applicable		No	—



Section **Roof & Headliner** completed successfully • Total Checkpoints: 8 • Passed: 8 • Minor: 0 • Major: 0 • Critical: 0

INFOTAINMENT SYSTEM

SECTION TITLE

INFOTAINMENT SYSTEM

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

18

PASSED

18

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Infotainment Display	PASS			No	✓
2	Touchscreen	N/A	Not Applicable		No	—
3	Android Auto	N/A	Not Applicable		No	—
4	Apple CarPlay	N/A	Not Applicable		No	—
5	Bluetooth	PASS			No	✓
6	Navigation	N/A	Not Applicable		No	—
7	Audio System	PASS			No	✓
8	Speakers	PASS			No	✓
9	Subwoofer	N/A	Not Applicable		No	—
10	Wireless Charging	N/A	Not Applicable		No	—
11	USB Connectivity	N/A	Not Applicable		No	—
12	360 Camera	N/A	Not Applicable		No	—
13	Reverse Camera	PASS			No	✓
14	Vehicle Settings Menu	PASS			No	✓
15	Connected Car Functions	N/A	Not Applicable		No	—
16	HU Internet Connectivity	N/A	Not Applicable		No	—
17	Voice Recognition Commands	N/A	Not Applicable		No	—
18	Phone Charging Sockets	PASS			No	✓

Section **Infotainment System** completed successfully • Total Checkpoints: 18 • Passed: 18 • Minor: 0 • Major: 0 • Critical: 0

HVAC SYSTEM

SECTION TITLE

HVAC SYSTEM

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

9

PASSED

9

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos



NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	AC Cooling	PASS			No	✓
2	Heating	PASS			No	✓
3	Blower	PASS			No	✓
4	Airflow Direction	PASS			No	✓
5	Rear AC Vents	N/A	Not Applicable		No	—
6	Climate Control	PASS			No	✓
7	Ventilated Seats HVAC Integration	N/A	Not Applicable		No	—
8	Air Purifier	N/A	Not Applicable		No	—
9	Cabin Filter Indicator	N/A	Not Applicable		No	—

Section **HVAC System** completed successfully • Total Checkpoints: 9 • Passed: 9 • Minor: 0 • Major: 0 • Critical: 0

MIRRORS

SECTION TITLE

MIRRORS

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

6

PASSED

6

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	IRVM	PASS			No	✓
2	Auto Dimming IRVM	N/A	Not Applicable		No	—
3	ORVM Adjustment	PASS			No	✓
4	ORVM Folding	N/A	Not Applicable		No	—
5	ORVM Heating	N/A	Not Applicable		No	—
6	Blind Spot Camera Display	N/A	Not Applicable		No	—

Section **Mirrors** completed successfully • Total Checkpoints: 6 • Passed: 6 • Minor: 0 • Major: 0 • Critical: 0

FEATURE VERIFICATION

SECTION TITLE

FEATURE VERIFICATION

COMPLETION

100% SECURE

PASS RATE SCORE

100%

CHECKPOINTS

16

PASSED

16

MINOR / MAJOR / CRITICAL

0 / 0 / 0

PHOTOS

0 Photos



NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	360 Camera	N/A	Not Applicable		No	—
2	Sunroof	N/A	Not Applicable		No	—
3	Panoramic Roof	N/A	Not Applicable		No	—
4	Ventilated Seats	N/A	Not Applicable		No	—
5	Wireless Charger	PASS			No	✓
6	Connected Car Tech	PASS			No	✓
7	Powered Tailgate	N/I	Not Inspected		No	—
8	Auto Dimming IRVM	N/A	Not Applicable		No	—
9	Air Purifier	N/A	Not Applicable		No	—
10	Massage Seats	N/A	Not Applicable		No	—
11	Heads-Up Display	N/A	Not Applicable		No	—
12	Digital Key	N/A	Not Applicable		No	—
13	V2L	N/A	Not Applicable		No	—
14	Remote Key	PASS			No	✓
15	Front Parking Sensors	N/A	Not Applicable		No	—
16	Rear Parking Sensors	PASS			No	✓

Section **Feature Verification** completed successfully • Total Checkpoints: 16 • Passed: 16 • Minor: 0 • Major: 0 • Critical: 0

EV SYSTEMS

SECTION TITLE	COMPLETION	PASS RATE SCORE
EV SYSTEMS	100% SECURE	100%
CHECKPOINTS 9	PASSED 9	MINOR / MAJOR / CRITICAL 0 / 0 / 0
		PHOTOS 0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Charge Port	N/I	Not Inspected		No	—
2	Charging Cable	N/I	Not Inspected		No	—
3	AC Charging Test	N/I	Not Inspected		No	—
4	DC Charging Test	N/I	Not Inspected		No	—
5	HV Cable Visual	N/I	Not Inspected		No	—
6	V2L Functionality	N/I	Not Inspected		No	—
7	HV Warning Labels	N/I	Not Inspected		No	—
8	Portable Charger Verification	N/I	Not Inspected		No	—
9	Wall Charger Verification	N/I	Not Inspected		No	—

Section **EV Systems** completed successfully • Total Checkpoints: 9 • Passed: 9 • Minor: 0 • Major: 0 • Critical: 0



ACCESSORIES

SECTION TITLE
ACCESSORIES

COMPLETION
100% SECURE

PASS RATE SCORE
100%

CHECKPOINTS
7

PASSED
7

MINOR / MAJOR / CRITICAL
0 / 0 / 0

PHOTOS
0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Floor Mats	PASS			No	✓
2	Toolkit Present	PASS			No	✓
3	Spare Wheel Present	PASS			No	✓
4	Jack Tool	PASS			No	✓
5	Spare Key	PASS			No	✓
6	Charger Present	N/A	Not Applicable		No	—
7	Dealer Accessories	N/A	Not Applicable		No	—

Section **Accessories** completed successfully • Total Checkpoints: 7 • Passed: 7 • Minor: 0 • Major: 0 • Critical: 0

ROAD TEST

SECTION TITLE
ROAD TEST

COMPLETION
100% SECURE

PASS RATE SCORE
100%

CHECKPOINTS
8

PASSED
8

MINOR / MAJOR / CRITICAL
0 / 0 / 0

PHOTOS
0 Photos

NO.	CHECKPOINT COMPONENT	RESULT	OBSERVATION	RECOMMENDATION	EVIDENCE	STATUS
1	Steering Feel	PASS			No	✓
2	Braking Response	PASS			No	✓
3	Suspension NVH	PASS			No	✓
4	Cabin Rattles	PASS			No	✓
5	Acceleration	PASS			No	✓
6	Regenerative Braking	N/A	Not Applicable		No	—
7	Vehicle Not Starting	PASS			No	✓
8	Gear Shifter Working	PASS			No	✓

Section **Road Test** completed successfully • Total Checkpoints: 8 • Passed: 8 • Minor: 0 • Major: 0 • Critical: 0

DEFECT EVIDENCE GALLERY - PAGE 1

SUPPORTING VISUAL EVIDENCE FOR FLAGGED OBSERVATIONS



ROOF (PHOTO 1)

MINOR

Observation: Scratch observed on Roof.
Recommendation: Cosmetic rectification before delivery.



WHEEL RL (PHOTO 1)

MINOR

Observation: Wheel design differs from specified vehicle variant on Wheel RL.
Recommendation: Dealer clarification required.



DEFECT EVIDENCE GALLERY - PAGE 2

SUPPORTING VISUAL EVIDENCE FOR FLAGGED OBSERVATIONS



DOOR HANDLES (PHOTO 1)

MINOR

Observation: Improper fitment of trim on Door Handles.

Recommendation: Dealer rectification before delivery.



SIGNATURES & VERIFICATION

This document represents the formal pre-delivery inspection (PDI) report compiled by INSPX Pro Inspection Platform. By signing below, the representing parties acknowledge the vehicle's structural, cosmetic, and functional condition as documented in this report.

Digitally Signed

Inspector Signature


INSPX Pro Certified

Customer Signature

Acknowledge Conditions

Dealership Representative

Authorized Signatory



Secure Cloud Verification

Scan this QR code to verify the authenticity of this report on the INSPX Pro Cloud Platform. Verify inspection database logs, photos, and digital timestamps.