

AGNI PARIKSHA - CERTIFICATE OF CONFORMANCE

Part ID: TEST_COMP

Lot ID: TEST_LOT

Verdict: FULL_BURN_IN

Risk Tier: MEDIUM

Top Contributing Parameters & Reasons:

- Slope exceeded threshold
- Lot variance extremely low

Metrics:

Measured 168h: N/A (Projected: 34.5)

Safety-slope margin: 0.05

Conformal interval: 2.3

Recommended Disposition:

FULL_BURN_IN

Routing Rationale: IMAGE_SENSOR/failing-family policy: mandatory 168h burn-in ? cannot certify at 24h