

Medical Image Analysis Report

Analysis Information

Date: 2025-09-14 19:07:48
Image Type: X-RAY
Image Path: 17baee9bfb9018e3d109ec63cb380e_big_gallery.jpeg

Image Statistics

Metric	Original	Processed
Dimensions	(630, 568)	(630, 568)
Mean Intensity	134.34	10.55
Std Deviation	71.94	12.48
Contrast	0.536	1.183
Entropy	7.69	4.83

Detected Abnormalities

Total Abnormalities Detected: 11
Total Affected Area: 650 pixels

Abnormality 1:

Type: fracture
Severity: medium
Area: 51 pixels

Abnormality 2:

Type: fracture
Severity: medium
Area: 81 pixels

Abnormality 3:

Type: fracture
Severity: medium
Area: 70 pixels

Abnormality 4:

Type: fracture
Severity: low
Area: 40 pixels

Abnormality 5:

Type: fracture
Severity: medium
Area: 54 pixels

Abnormality 6:

Type: fracture
Severity: medium
Area: 66 pixels

Abnormality 7:

Type: fracture
Severity: medium
Area: 62 pixels

Abnormality 8:

Type: fracture
Severity: medium
Area: 79 pixels

Abnormality 9:

Type: fracture
Severity: medium
Area: 59 pixels

Abnormality 10:

Type: fracture
Severity: low
Area: 44 pixels

Disclaimer: This analysis is for research and educational purposes only. Results should not be used for medical diagnosis without professional review.