



# Lizpa Landscaping, Inc.

Bill To: Enclave C/O  
Sentry Management Inc.  
  
2180 W. State Rd. 434  
Address: Suite 5000 Longwood, FL  
32779

Phone: 407-788-6700 ext 51209

Invoice #: 1806

Fax: 407-788-7488

Service Address: Enclave  
1397 Benevolent St.  
Maitland, FL 32751

Email: mpogue@sentrymgt.com

Invoice Date: 12/28/2025

| Qty                                                | Description                                                                                                                                                                                                                                                                                                           |          | Price             |
|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-------------------|
|                                                    | Timer replacement, parts and labor included                                                                                                                                                                                                                                                                           | \$250.00 | <b>\$1,735.00</b> |
|                                                    | Parts for inspection repairs                                                                                                                                                                                                                                                                                          | \$235.00 |                   |
|                                                    | Hours of labor for tech for inspection and repairs                                                                                                                                                                                                                                                                    | \$600.00 |                   |
|                                                    | Parts and labor for broken pipes and reinstalled bubblers on Caring Ct                                                                                                                                                                                                                                                | \$150.00 |                   |
|                                                    | Zone 18- Added a rotor for coverage of large dry spot behind mail station, added a                                                                                                                                                                                                                                    | \$200.00 |                   |
|                                                    | bubbler for new palm behind mail station. Approved by Mr Charlie, parts & labor in                                                                                                                                                                                                                                    |          |                   |
|                                                    | Hours of labor for running system zone by zone, combining zones and adjusting                                                                                                                                                                                                                                         | \$300.00 |                   |
|                                                    | pressure to prevent pump cycling                                                                                                                                                                                                                                                                                      |          |                   |
|                                                    | After replacing the broken 5HP booster pump near the entrance and cycle stop valve an inspection was performed by request of Mr Charlie. The timer that controls the flush valve in the pump station by the lake was also replaced, also approved by Mr Charlie.                                                      |          |                   |
|                                                    | Mr Charlie Requested us to repair broken pipes damaged by people taking out 2 palm trees on Caring Ct. Reinstalled 2 bubbles for the 2 new trees that are going to be installed.                                                                                                                                      |          |                   |
|                                                    | Inspection report                                                                                                                                                                                                                                                                                                     |          |                   |
|                                                    | Zone 4- Repaired a broken riser, replaced broken head                                                                                                                                                                                                                                                                 |          |                   |
|                                                    | Zone 5- Replaced a broken head, riser and repaired a 2 ½" broken lateral pipe                                                                                                                                                                                                                                         |          |                   |
|                                                    | Zone 13- Replaced broken head                                                                                                                                                                                                                                                                                         |          |                   |
|                                                    | Zone 17- Replaced a clogged nozzle                                                                                                                                                                                                                                                                                    |          |                   |
|                                                    | Zone 20- Repaired ½" broken pipe, replaced broken sprayer, replaced 2 nozzles                                                                                                                                                                                                                                         |          |                   |
|                                                    | Zone 23- Replaced a clogged nozzle                                                                                                                                                                                                                                                                                    |          |                   |
|                                                    | Zone 25- Repaired broken ½" lateral                                                                                                                                                                                                                                                                                   |          |                   |
|                                                    | Zone 27- Replaced 2 broken sprayers, 2 clogged nozzles                                                                                                                                                                                                                                                                |          |                   |
|                                                    | Zone 36- Replaced broken sprayer                                                                                                                                                                                                                                                                                      |          |                   |
|                                                    | Zone 37- Repaired broken ½" lateral                                                                                                                                                                                                                                                                                   |          |                   |
|                                                    | Note: it took 2 days with 2 people going zone by zone adjusting the pressure and combining some zones to ensure that the system was running with the proper pressure and that the pumps were not cycling. Only 4 hours of labor will be charged to compensate for the time spent. See new map attached for reference. |          |                   |
| Make all checks payable to Lizpa Landscaping, Inc. |                                                                                                                                                                                                                                                                                                                       |          |                   |
| Thank you for your business!!                      |                                                                                                                                                                                                                                                                                                                       | TOTAL    | <b>\$1,735.00</b> |