



Qty	Description		Price
	Performed inspection Zone 3-inoperable. Located and repaired the valve and replaced drip filter. To repaired 2 broken drip pipes. Zone 4- To repaired broken drip pipe. Zone 5- To repaired broken drip pipe Zone 8- Replaced broken nozzle. Zone 11- Inoperable. To located and repaired valve		
	See map attached. Green area is zone 3, valve is infront of building #71. Marked "3" on map Blue area is zone 11. Valve is between buildings 121 and 129. Marked "11" on map "x" is where broken drip pipes were		
	Labor		\$250.00
	Parts		\$350.00
Make all checks payable to Lizpa Landscaping, Inc.			
Thank you for your business!!		TOTAL	\$600.00