

Gold Standard Service Corp.

P.O. BOX 4831
Rancho Cucamonga, CA 91729

gold-standard@hotmail.com

(877)313-3552 Of...



Invoice

Date: 12/8/2021

Invoice # 36645

Work Order # 36645

Bill To

Total Transportation & Distribution
210 East Lambert Road,
Fullerton, CA 9283

Ship To

210 E. Lambert Rd.
Fullerton, CA

P.O. # LS210-P7-51520

Unit # P7

Hour Meter: 2910

Serial # EASI-00-AE25743

Terms: Due on receipt

Due Date: 12/8/2021

Ship Date 12/8/2021 Tech: DK

Model: RaymondEASI-OPC30TT

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: Wire guidance not working. Found damage to cable. Repaired cable. Unit still doesn't track. Julio stated Unit not configured for guidance. return to service.	4	112.50	450.00

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.
P. O. Box 4831
Rancho Cucamonga, CA 91729

Subtotal	\$450.00
Sales Tax (7.75%)	\$0.00
Total	\$450.00
Payments/Credits	\$0.00
	\$450.00