

**Gold Standard Service Corp.****P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



# Invoice

**Date:** 1/13/2022**Invoice #** 36760**Work Order #** 36760**Bill To**Total Transportation & Distribution  
210 East Lambert Road,  
Fullerton, CA 9283**Ship To**11937 Woodruff  
Downey, CA**P.O. #** KP11937-S3**Unit #** S3**Hour Meter:** 18714**Serial #** SA-03-03235**Terms:** Due on receipt**Due Date:** 1/13/2022**Ship Date** 1/13/2022 **Tech:** JR**Model:** RaymondSACSR30T

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: Check code 23. Replace Q1 power transistor. Test OK.	1.75	112.50	196.88
Transistor Q1 Kit 1133904	1	957.45	957.45T

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.  
P. O. Box 4831  
Rancho Cucamonga, CA 91729

<b>Subtotal</b>	\$1,154.33
<b>Sales Tax (10.0%)</b>	\$95.75
<b>Total</b>	\$1,250.08
<b>Payments/Credits</b>	\$0.00
	\$1,250.08