

Gold Standard Service Corp.**P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



Invoice

Date: 5/25/2022**Invoice #** 37389**Work Order #** 37389**Bill To**Total Transportation & Distribution
210 East Lambert Road,
Fullerton, CA 92833**Ship To**210 E. Lambert Rd.
Fullerton, CA**P.O. #** LS210-F7-51520**Unit #** F7**Hour Meter:** 648**Serial #** 35359**Terms:** Due on receipt**Due Date:** 5/25/2022**Ship Date** 5/24/2022 **Tech:** DK**Model:** Toyota8FGCU25

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: 5/20 cleaned off site. Filled used unit and Radiator leaking. Removed and ordered new. 5/24 Installed and filled. Returned unit to service.	7	112.50	787.50
Antifreeze 550162	2	90.75	181.50T
Radiator New	1	481.25	481.25T

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.
P. O. Box 4831
Rancho Cucamonga, CA 91729

Subtotal	\$1,450.25
Sales Tax (7.75%)	\$51.36
Total	\$1,501.61
Payments/Credits	\$0.00
	\$1,501.61