

Gold Standard Service Corp.**P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



Invoice

Date: 1/26/2022**Invoice #** 55879**Work Order #** 55879**Bill To**Total Transportation & Distribution
210 East Lambert Road,
Fullerton, CA 9283**Ship To**210 E. Lambert Rd.
Fullerton, CA**P.O. #** LS210-P17-51530**Unit #** P17**Hour Meter:** 2669**Serial #** 540-15-B22920**Terms:** Due on receipt**Due Date:** 1/26/2022**Ship Date** 1/26/2022 **Tech:** DK**Model:** Raymond540OPC30TT

Description	Qty	Rate	Amount
Perform scheduled maintenance on orderpicker: Remove covers and blow off with compressed air. Checked all fluids and grease all fittings. Wiped down unit.	1	113.00	113.00

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.
P. O. Box 4831
Rancho Cucamonga, CA 91729

Subtotal	\$113.00
Sales Tax (7.75%)	\$0.00
Total	\$113.00
Payments/Credits	\$0.00
	\$113.00