Gold Standard Service Corp.

P.O. BOX 4831 Rancho Cucamonga, CA 91729

gold-standard@hotmail.com (877)313-3552 Of...

Bill To

P.O. #

Unit # T103

Hour Meter: 21903

Serial # 970-11-01561ren

Total Transportation & Distribution 210 East Lambert Road, Fullerton, CA 9283

LS210-T103-51530

Invoice

Gold Standard
Service

Date: 1/31/2022

Invoice # 36681

Work Order # 36681

Ship To

210 E. Lambert Rd. Fullerton, CA

Terms: Due on receipt

Due Date: 1/31/2022

Ship Date 1/31/2022 Tech: DK

Model: Raymond970-CSR30T

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: Repaired broken cover on Fan. Customer Damage	2	112.50	225.00

Thank you for choosing Gold Standard Service for all your material handling needs.	Subtotal	\$225.00
	Sales Tax (7.75%)	\$0.00
	Total	\$225.00
Remit To: Gold Standard Service Corp. P. O. Box 4831	Payments/Credits	\$0.00
Rancho Cucamonga, CA 91729		\$225.00