

**Gold Standard Service Corp.****P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



# Invoice

**Date:** 6/3/2022**Invoice #** 36909**Work Order #** 36909**Bill To**Total Transportation & Distribution  
210 East Lambert Road,  
Fullerton, CA 92833**Ship To**210 E. Lambert Rd.  
Fullerton, CA**P.O. #** LS210-S8-51520**Unit #** S8**Hour Meter:** 17466**Serial #** SA-07-05671**Terms:** Due on receipt**Due Date:** 6/3/2022**Ship Date** 6/3/2022 **Tech:** JR**Model:** RaymondSACSR30T

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: Check lift problem. Fork continue lifting after releasing lift knob. Install temporary prop valve and learn weight. Test OK	2	121.50	243.00

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.  
P. O. Box 4831  
Rancho Cucamonga, CA 91729

<b>Subtotal</b>	\$243.00
<b>Sales Tax (9.5%)</b>	\$0.00
<b>Total</b>	\$243.00
<b>Payments/Credits</b>	\$0.00
	\$243.00