# **Report Generated by Test Manager**

Title:

**Author:** 

Date: 06-Dec-2021 12:39:48

## **Test Environment**

Platform: PCWIN64 MATLAB: (R2021b)

## Summary

| Name                | Outcome | Duration (Seconds) |
|---------------------|---------|--------------------|
| □ <u>Demo_video</u> | 2 🗷     | 1.305              |
| New Test Suite 1    | 2 🗷     | 1.305              |
|                     | •       | 0.696              |
| ■ <u>SS</u>         | •       | 0.578              |

## Demo\_video

#### **Test Result Information**

Result Type: Test File Result

Parent: None

Start Time: 06-Dec-2021 12:39:46 End Time: 06-Dec-2021 12:39:47 Outcome: Total: 2, Passed: 2

#### **Test Suite Information**

Name: Demo\_video

**Back to Report Summary** 

## **New Test Suite 1**

## **Test Result Information**

Result Type: Test Suite Result Parent: Demo\_video

Start Time: 06-Dec-2021 12:39:46 End Time: 06-Dec-2021 12:39:47 Outcome: Total: 2, Passed: 2

#### **Test Suite Information**

Name: New Test Suite 1

**Back to Report Summary** 

## TL

#### **Test Result Information**

Result Type: Test Case Result
Parent: New Test Suite 1
Start Time: 06-Dec-2021 12:3

Start Time: 06-Dec-2021 12:39:46 End Time: 06-Dec-2021 12:39:46 Outcome: Passed

## **Test Case Information**

Name: TL


Type: **Baseline Test** 

Test Case Requirements
Description: Number of Traffic Lights
Document: Demo\_test\_req.slreqx

## **Verify Result**

| Name  | Lin | ık to Plo<br>t |
|---|-----|----------------|
| Test Assessment Block//VerifyThis:verify(numel(TL)==1)        | i - | <u>Link</u>    |
| Test Assessment Block//VerifyThis:verify(numel(Stop_Sign)==1) | i i | <u>Link</u>    |

| Name  |
|---|
| Test Assessment Block//VerifyThis:verify(numel(TL)==1)        |
| Test Assessment Block//VerifyThis:verify(numel(Stop_Sign)==1) |



Back to Report SummaryBack to Signal Summary

## **Simulation**

## **System Under Test Information**

Model: RegsGroundTruth

Harness: RegsGroundTruth\_Harness2

Harness Owner: ReqsGroundTruth/Lights and Signs ID

Release: Current Simulation Mode: normal

Override SIL or PIL

Mode:

Configuration Set: Configuration1

Start Time: 0

Stop Time: 3.099999999999783

0

Checksum: 3150108377 3559391656 3130211307 4191073157

#### Test Logs:

No baseline criteria evaluation performed as no baseline data is available for this test.

## **Back to Report Summary**

## SS

#### **Test Result Information**

Result Type: Test Case Result
Parent: New Test Suite 1
Start Time: 06-Dec-2021 12:39:46
End Time: 06-Dec-2021 12:39:47

Outcome: Passed

#### **Test Case Information**

Name: SS

Type: Baseline Test


## **Test Case Requirements**

Description: Number of stop signs
Document: Demo\_test\_req.slreqx

## **Verify Result**

|      | Link to Plo |
|------|-------------|
| Name |             |

| Test Assessment Block//VerifyThis:verify(numel(TL)==1)        | į.     | <u>Link</u> |
|---|--------|-------------|
| Test Assessment Block//VerifyThis:verify(numel(Stop_Sign)==1) | Į<br>Į | <u>Link</u> |



Back to Report SummaryBack to Signal Summary

#### **Simulation**

## **System Under Test Information**

Model: ReqsGroundTruth

Harness: ReqsGroundTruth\_Harness2

Harness Owner: RegsGroundTruth/Lights and Signs ID

Release: Current Simulation Mode: normal

Override SIL or PIL 0

Mode:

Configuration Set: Configuration1

Start Time: 0

Stop Time: 3.099999999999783

Checksum: 3150108377 3559391656 3130211307 4191073157

## Test Logs:

No baseline criteria evaluation performed as no baseline data is available for this test.

**Back to Report Summary**