ALOKHANDWALA

**ALOKHANDWALA**
**SCAFFOLDING & HEAVY SHORING SOLUTIONS DIVISION**
4th Floor, Office No. 401 Sapphire Square Tower, Square Indore, MP, India
Yard: Taloja Central Scaffolding Yard, Navi Mumbai / Maharashtra | Ph: +91 8818852722 | alokhandwala.sh@gmail.com
**GSTIN: 23AABCA1234F1Z5 | PAN: AABCA1234F**

**INSTALLATION HANDOVER**

**INST-AW-SCF-000001**
Date of Issue: 16 Nov 2026

# SCAFFOLDING INSTALLATION & HANDOVER CERTIFICATE

## CUSTOMER / CLIENT INFORMATION

**Godrej Properties Ltd**
Contact: Godrej Properties Ltd | +91 98200 11223
Email: godrejpropertiesltd@scaffold-client.com
Address: Vikhroli East, Mumbai

**GSTIN: Unregistered / N/A** CUST-0002

## PROJECT SITE & EXECUTION LOCATION

**Godrej Vistas Tower C**
Location: Vikhroli East, Mumbai

Assigned Supervisor: **Mustafa Alokhandwala (Supervisor)**
Site ID: site-1793454771167

**Project Code: AW-SCF-000001** SITE-0001

## SITE EXECUTION & SUPERVISORY RECORD

Assigned Supervisor: **Mustafa Alokhandwala (Supervisor)**
Executing Supervisor: **Mustafa Alokhandwala (Lead)**
Active Rental Period: **16 Nov 2026 to 16 Dec 2026**

**Erection Crew & Certified Riggers:**
Ramesh Yadav (Lead Rigger), Suresh Patil (Scaffolder)

## DIMENSIONAL COMPLIANCE & MEASUREMENT VERIFICATION

Confirmed Dimensions: **30m (L) × 10m (W) × 20m (H)**
Actual Installed: **30m (L) × 10m (W) × 20m (H)**
Verification Status: **Fully Compliant (0% Variance)**
Inspection Remarks: **Exact physical match**

| # | Item Code | Scaffolding Component | Unit | Planned | Installed | Variance | Status |
|---|---|---|---|---|---|---|---|
| 1 | **V-10FT-3M** | VERTICAL 10FT/3MTR | NOS | 10 | **10** | 0 | **Installed & Secured** |

## SITE PHOTOGRAPHS & ERECTION EVIDENCE

*No installation images uploaded for this project.*

## SITE HANDOVER, CHALLAN APPROVAL & MATERIAL RESPONSIBILITY TERMS

**[11] Challan & Custody:** Customer must verify and approve the delivery challan of all materials supplied. Safekeeping of materials during rental is customer responsibility;
**[9] Damage / Loss:** Customer is liable for any damage, loss, or misplacement of scaffolding materials at prevailing replacement value on assessment date.
**[10] Post-Install Visits:** Any site visits requested after completion of installation will be chargeable based on location and scope.
**[2/8] 28-Day Cycle:** Rentals run on a 28-day cycle. Exceeding 28 days by even 1 day incurs applicable monthly charge, payable on next day after 28 days.

## STRUCTURAL SAFETY INSPECTION & HANDOVER DECLARATION

This certifies that the scaffolding structure described above has been erected, plumbed, leveled, and tied in sound structural condition according to IS 2750/IS 4014 scaffolding standards. All cup-lock joints, base plates, and ledgers have been verified.

## CUSTOMER SITE INSPECTION & ACCEPTANCE

I confirm structural handover and acceptance of installed scaffolding:

Client Site Engineer / Authorized Name, Signature & Stamp

## ALOKHANDWALA SUPERVISOR & ERECTION LEAD

Inspected by: Mustafa Alokhandwala

Certified Site Supervisor Signature & Company Stamp