
Road Damage Control Department

Government office

Address city

(123) 456-7890

Road damage report

Description : Pothole was found here

GENERAL DETAILS

Location	Bandra Kurla Complex Road, G Block, H/E Ward, Zone 3, Mumbai, Mumbai Suburban, Maharashtra, 400 051, India
Type of Damage	Shallow Pothole
Date Reported	2019-02-10-18:04:15
Priority	Severe
Reported by	aniruddh
Current Status	Not Fixed

IMAGES


First Image :



Second Image :



Feedback image :



ENGINEERING PARAMETERS

Please note that the parameters calculated in this section are calculated autonomously based on image data given as input.

* Invoice generated separately.