Road Damage Control Department

Government office Address city (123) 456-7890

Road damage report

Description: This pothole was found on the mail road (BKC) and is affecting a lot of lives on daily basis. We need to resolve this as soon as possible!

GENERAL DETAILS

Location Bandra Kurla Complex Road, G Block, H/E

Ward, Zone 3, Mumbai, Mumbai Suburban,

Maharashtra, 400 051, India

Type of Damage Shallow Pothole

Date Reported 2019-02-15-21:37:20

Priority Severe

Reported by aniruddh

Current Status Not Fixed

IMAGES


First Image:



Second Image:



Feedback image:



ENGINEERING PARAMETERS

Please note that the parameters calculated in this section are calculated autonomously based on image data given as input.

^{*} Invoice generated separately.