

---

## Road Damage Control Department

Government office

Address city

(123) 456-7890

# Road damage report


Description : A bottle was found!

## GENERAL DETAILS

Location	Kopar Khairne, Navi Mumbai, Thane, Maharashtra, 400710, India
Type of Damage	Shallow Pothole
Date Reported	2019-02-15-18:00:26
Priority	Severe
Reported by	aniruddh
Current Status	Not Fixed

## IMAGES


First Image :



Second Image :



Feedback image :



## ENGINEERING PARAMETERS

Please note that the parameters calculated in this section are calculated autonomously based on image data given as input.

\* Invoice generated separately.