

---

## Road Damage Control Department

Government office

Address city

(123) 456-7890

# Road damage report

Description : Pothole was found in this place. Kindly check.

## GENERAL DETAILS

Location	Bandra Kurla Complex Road, G Block, H/E Ward, Zone 3, Mumbai, Mumbai Suburban, Maharashtra, 400 051, India
Type of Damage	Shallow Pothole
Date Reported	2019-02-04-19:49:18
Priority	Severe
Reported by	aniruddh
Current Status	Not Fixed

## IMAGES


First Image :



Second Image :



Feedback image :



## ENGINEERING PARAMETERS

Please note that the parameters calculated in this section are calculated autonomously based on image data given as input.

\* Invoice generated separately.