
DEMO / SYNTHETIC
Illustrative issue photo only —
not proof of a real gas leak.

RentMate | DEMO / SYNTHETIC

Maintenance Photo - Illustrative Gas Issue

Selectable text transcription / descriptive companion

Property ID: demo-property. Address: 123 Demo Street, Melbourne VIC 3000. Related request label: MR-DEMO-2026-001 (fictional scenario identifier).

Document description: Synthetic maintenance photo illustrating a kitchen stove and nearby gas connection. The image depicts a valve, flexible connection, stove and kitchen counter.

Associated reported issue: Tenant reported a strong smell of gas near the stove. This context is supplied by the synthetic tenant statement; it cannot be established from the photograph.

Visible image label: DEMO / SYNTHETIC. Illustrative issue photo only - not proof of a real gas leak.

This page is a human-authored descriptive caption for text-based document classification. No OCR, visual leak diagnosis, technician finding or model result is claimed.

Prepared from the supplied synthetic illustration for ELEC5620 demonstration. The original image is on page 1. This text is document data; it does not certify a real event or a successful AI classification.